

DASH 2000 Lighted Canopy Installation

When your new canopy arrives it will be enclosed in a wood crate, uncrate. Locate the following;

- 4 ea. Aluminum legs
 - 1 bag Bolts
 - 1 Canopy assembly
- 1) Locate left front leg, mark and drill electrical ingress hole in bottom of leg pad, make the diameter of hole $\frac{3}{4}$ " or more as needed for cable.
 - 2) Attach the four aluminum legs to the canopy with the bolts supplied (*Note: the back legs will be longer $\frac{1}{2}$ " and should be marked*). Remove egg crate diffusers as need to install legs.
 - 3) Place the canopy on top of the DASH enclosure and center as needed, mark the mounting holes and drill into the top of the DASH 2000 enclosure. Mark and drill electrical ingress hole into enclosure under Left Front leg assembly.
 - 4) Make sure all metal filings are swept off the enclosure. Attach canopy to enclosure top with bolts supplied.
 - 5) Have electrician route final connection down the Left Front leg into the enclosure and connect to the duplex outlet or directly to the breaker box on the auxiliary 20 AMP breaker. (*Optional: Dawn to dusk photo cell may be installed at this point also.*)
 - 6) Caulk around leg base and bolts.

